



State of Utah

Department of Natural Resources

ROBERT L. MORGAN Executive Director

Division of Oil, Gas & Mining

LOWELL P. BRAXTON Division Director OLENE S. WALKER Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

May 25, 2004

CERTIFIED RETURN RECEIPT 7099 3400 0016 8896 0259

Mr. Mark Willes BMW Stone, Inc. 2565 South State Road 32 Wanship, Utah 84017-9747

Subject: Five-Year Review of Reclamation Surety Estimate, BMW Stone, Inc.,

Browns Canyon Rock, M/043/021, Summit County, Utah

Dear Mr. Willes:

The Division is performing the periodic review of reclamation surety estimates to verify their accuracy and make adjustments for escalation and any site modifications that could result in a change of the surety amount presently being held for the site. We require that surety estimates being held by the State include a five year escalation and be reviewed every five years.

The reclamation surety for BMW Stone, Inc's Brown Canyon Rock Quarry is due for review as of 2004. To assist us in this review, we request an updated map of your site showing current surface facilities and disturbances. Please provide the updated map at a scale of not less than 1 inch = 500 feet, which includes: buildings, stationary mining/processing equipment, roads, utilities, power lines, drainage structures (i.e. berms, culverts, etc.), topsoil, ore and product storage areas, overburden/waste dumps, tailings or processed waste facilities, solid and liquid wastes, and wastewater discharge treatment and containment facilities, etc. This map should include all areas which have been affected by this operation to date. Please ignore items listed above which do not apply to your site.

If any reclamation has been completed on the site since the last surety estimate review, please provide a separate map of the same scale as the site map, clearly identifying these reclaimed areas, the acreage affected, and the date of the reclamation. Please cross-hatch or shade the areas to identify the reclamation



Mark Wiles Page 2 of 2 M/043/021 May 24, 2004

treatments (i.e. ripping, regrading, mulching, seeding, etc.) which have been applied.

Please provide this information within the next 60 days or no later than July 24, 2004. If you are unable to meet this timeframe, please contact the Division with justification for requesting additional time. Thank you for providing this information to assist us in our surety estimate review. If you have any questions concerning this letter, please contact Doug Jensen at (801) 538-5382.

Sincerely,

D. Wayne Hedberg

Permit Supervisor

Minerals Regulatory Program

DWH:DJ:jb
O:\M043-Summit\M0430021-BrownsCynRock-BMW\Final\Syr-rev-05242004.doc